




ISO

**CONTROCERNIERA A
SQUADRA ORIZZONTALE
A BASE QUADRA**



CODICE	A ₀ ⁺²	B	C ₀ ^{±0,2}	ØD	E	ØF _(B13)	G ₀ ^{±0,2}	H ₀ ^{+0,5}	ØI _(H11)	ØJ	K _{-0,6} ^{-0,2}
CCIS032	45	10	32,5	7	10	30	7	32	10	22	26
CCIS040	52	10	38	7	12	35	7	36	12	26	28
CCIS050	65	12	46,5	9	12	40	7	45	12	26	32
CCIS063	75	12	56,5	9	15	45	7	50	16	34	40
CCIS080	95	16	72	11	15	45	9	63	16	34	50
CCIS100	115	16	89	11	22	55	9	73	20	42	60